Inspection Report

Name of Work	: Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-PMT(9176)/WO/492/2013-14 Dated: 22.02.2014.
Agency	: P. Kumar Swamy
B.R. No & Date	: 431/2013-14 Dated: 29.03.2014
Bill Amount	: 19,42,275.77
Job Code	: 011-14-000011
P. Code	: P-1771
Date of Inspection	: 22-10-15

The above said Work - Improvements to Roads and Construction of Culverts at M.S. palya 2nd Stage Masidi Main Road and Cross Roads in Ward No (11) Kuvempunagara - Vidyaranyapura - has been shown by the concerned JE.

The above said has been inspected along with the concerned JE.

The Measurements are checked by me and the found Satisfactory

The Work done is Satisfactory.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Sketch for the Work of Impovements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.



Junior Engineer
ward No. 11

Verified

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(R&D)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.





G.M.MUNIYAPPA
B.E.(ELECT.),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E.,(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division

G.M.MUNIYAPPA,
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Improvements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.



G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
WORKS DEPARTMENT